

MSIL: COS: NSE&BSE: 2022/09_07

16th September, 2022

Vice President
National Stock Exchange of India Ltd.
"Exchange Plaza",
Bandra- Kurla Complex,
Bandra (E)
Mumbai - 400 051

General Manager
Department of Corporate Services
BSE Limited
Phiroze Jeejeebhoy Towers
Dalal Street,
Mumbai 400001

Sub: Maruti Suzuki to recall 5002 Super Carry Vehicles

Dear Sirs,

The Company has announced to recall 5,002 Super Carry vehicles manufactured between 4th May, 2022 and 30th July, 2022.

The recall is being undertaken for inspection and torquing of a bolt attached to seat belt buckle bracket of co-driver seat. It is suspected that there is a possible defect in bolt torquing, which in a rare case, may loosen in the long run.

Affected vehicle owners will be receiving communication from Maruti Suzuki authorized workshops for inspection and repair (free of cost).

Customers may also visit the 'Imp Customer Info' section on the Company website www.marutisuzuki.com and fill in their vehicle chassis number (MA3 followed by 14-digit alpha-numeric number) to check if their vehicle needs any attention in this regard. The chassis number is embossed on the vehicle ID plate and is also mentioned in the vehicle invoice/registration documents.

Kindly same the same on record.

Thanking you,

Yours truly,

For **Maruti Suzuki India Limited**

Sanjeev Grover
Executive Vice President
& Company Secretary

MARUTI SUZUKI INDIA LIMITED

Head Office:
Maruti Suzuki India Limited,
1, Nelson Mandela Road, Vasant Kunj,
New Delhi - 110070, India.
Tel: 011- 46781000, Fax: 011-46150275/46150276
E-mail id: contact@maruti.co.in, www.marutisuzuki.com

Gurgaon Plant:
Maruti Suzuki India Limited,
Old Palam Gurgaon Road,
Gurgaon - 122015, Haryana, India. Tel:
0124-2346721, Fax: 0124-2341304

Manesar Plant:
Maruti Suzuki India Limited,
Plot No.1, Phase - 3A, IMT Manesar,
Gurgaon - 122051, Haryana, India. Tel:
0124-4884000, Fax: 0124-4884199